REPO	RT DOCU	MENTAT	ION PAGE		Form Approved OMB No. 0704-0188	
Public reporting bu	rden for this collection of	information is estimated to	average 1 hour per response, in	including the time for reviewing instructions, searching existing data sources, gathering and		
maintaining the dat including suggestio Davis Highway Su	a needed, and completing ns for reducing this burde ite 1204 Arlington VA	and reviewing this collec n, to Department of Defer 22202-4302. Respondents	tion of information. Send comm use, Washington Headquarters S a should be aware that notwiths	nents regarding this burd Services, Directorate for tranding any other provision	en estimate or any other aspect of this collection of information, Information Operations and Reports (0704-0188), 1215 Jefferson on of law, no person shall be subject to any penalty for failing to JRN YOUR FORM TO THE ABOVE ADDRESS.	
1. REPORT D		2. REPORT T Viewgraphs		3. DATES COV		
4. TITLE ANI	SUBTITLE			5a. CONTRAC	r number	
NDE R&D at	NAWC			5b. GRANT NU	MBER	
				5c. PROGRAM	ELEMENT NUMBER	
6. AUTHOR(S	5)			5d. PROJECT N	NUMBER	
Ignacio Perez				5e. TASK NUM	IBER	
				5f. WORK UNI	T NUMBER	
7. PERFORM	ING ORGANIZAT	ION NAME(S) AN	D ADDRESS(ES)	8. PERFORMIN	IG ORGANIZATION REPORT NUMBER	
22347 Cedar I	fare Center Aircraf Point Road, Unit #6 r, Maryland 20670-					
9. SPONSORI	NG/MONITORING	G AGENCY NAME	E(S) AND	10. SPONSOR/I	MONITOR'S ACRONYM(S)	
ADDRESS(ES	5)			11 (220)(30)	MONTEONIS PUROPE NEL APER (S)	
				11. SPONSOR/I	MONITOR'S REPORT NUMBER(S)	
12. DISTRIBU	JTION/AVAILABI	LITY STATEMEN	T			
Approved for	public release; distr	ibution is unlimited	1.			
13. SUPPLEM	IENTARY NOTES					
14. ABSTRAC	CT					
					•	
			· · · · · · · · · · · · · · · · · · ·			
15. SUBJECT	TERMS					
16. SECURIT	Y CLASSIFICATION	ON OF:	17. LIMITATION OF ABSTRACT	18. NUMBER OF PAGES	19a. NAME OF RESPONSIBLE PERSON Ignacio Perez	
a. REPORT	b. ABSTRACT	c. THIS PAGE			19b. TELEPHONE NUMBER (include area	
Unclassified	Unclassified	Unclassified	SAR	41	code) (301) 342-8074	

Standard Form 298 (Rev. 8-98) Prescribed by ANSI Std. Z39-18






NDE R&D at NAWC

Naval Air Warfare Center, Aircraft Division Patuxent River, MD October 16, 2000




Team





Dr. William Frazier (Branch leader)



Dr. Ignacio Perez



RP

Paul Kulowitch

(team leader)

Ron Palchinsky

John Lundeen

Rachel Santos

William Davis

RS







R



20



Gwynn McConnell Jack O'Brien Contractors

GMc

Dr. Huang-Liang Cui Dr. Assad Youssef **Summer Faculty**


NAVAL AIR WARFARE CENTER, AIRCRAFT DIVISION, PAUXENT RIVER, MD



R&D




Thermography



 Non-Contact Wide Area

Ultrasonic Imaging

- •Fast
- Cuverd Surfaces




Optical Fiber Technology

1.0" Compound Acoustic Lens Pulse-Echo Probe Pliable Polyeurothane —— Covered Wear Plate Corrosion pit

LCD Display

Heat Damage Detection - LPF

Umbilical Cable



NAVAL AIR WARFARE CENTER, AIRCRAFT DIVISION, PAUXENT RIVER, MD





Thermography




INFRARED THERMOGRAPHY



- Problem: Rapid and reliable detection of hidden corrosion, impact damage, water entrapment.

 Solution: Development and Transition Infrared Thermography to I- and D- level maintenance programs
- Advantages (compared to ultrasonic inspection):
- NO COUPLANT REQUIRED
- WIDE AREA INSPECTION METHOD
- INSENSITIVE TO CURVATURE
- EASY TO INTERPRET
- PORTABLE
- NO SAFETY REQUIREMENTS.
- Cost Savings:
- 30 ft²/min INSPECTION RATE (COMPARED TO 1 ft²/min FOR UT
- CAN DETECT CORROSION WITH OUT PAINT REMOVAL
- (DOES NOT GENERATE WASTE PRODUCTS)
- CAN DETECT CORROSION INSIDE LAP JOINT
- \$ 25M/Aircraft POTENTIAL COST SAVINGS FOR F-18
 E/F OVER THE LIFE OF THE AIRCRAFT (Boeing Data)
- Transition Potential: P-3C, C-130, KC-135, F-18 C/D, JSF








Thermographic Modeling














Depth of Resolution






NAVAL AIR WARFARE CENTER, AIRCRAFT DIVISION, PAUXENT RIVER, MD



Depth of Resolution






NAVAL AIR WARFARE CENTER, AIRCRAFT DIVISION, PAUXENT RIVER, MD



Depth of Resolution





NAVAL AIR WARFARE CENTER, AIRCRAFT DIVISION, PAUXENT RIVER, MD



Thermography Water Entrapment




- Water entrapment is a major cause of material degradation.
- In metals it leads to corrosion.
- In honeycomb structures it can lead to face sheet separation during freezing
- In bonded structures is a primary mechanism for bond degradation
- In composites it adds unnecessary weight to the structure and can lead to material degradation especially after freezing and thawing.




SAMPLES PREPARATION





D=3/8"	
D=1/4"	
D=1/8"	




A Commence of the Commence of		4.0	
	4.55		
	*		d
			Edill Signi
			(i)
÷ .			
**			

perimental Pa	Experimental Parameters for Drops and Panels	s and Panels
Al Thickness	Straw Diameter Water Height	Water Height
$t_o = 1/32$ "	D = 1/8"	,0 = p
$t_0 = 1/16$ "	D = 1/4"	d = 1/16"
$t_0 = 1/8$ "	D = 3/8"	d = 1/8"
	D = 1/2"	d = 3/16"
		d = 1/4"



Experimental Data








Experimental Data II



Maximum Contrast



- The thinner the aluminum substrate the larger the contrast
- The smaller the straw diameter the smaller the contrast
- The amount of water in the straw does not affect the contrast (error bars small)



LATERAL HEAT FLOW EFFECTS (effective contact conductivity model)



Contrast curve

$$(t) = \frac{Q}{\rho_1 c_1 \cdot t_o \cdot \sqrt{(1+a+r)^2 - 4ar}} \left(e^{\frac{h \cdot \lambda_3}{\rho_1 c_1 \cdot t_o}} - e^{\frac{h \cdot \lambda_2}{\rho_1 c_1 \cdot t_o}} \right)$$

Peak contrast

$$\Delta T_{\text{peak}} = \frac{Q}{\rho_1 c_1 t_o (1 + a + r + \sqrt{(1 + a + r)^2 - 4ar})} \cdot \frac{1 + a + r - \sqrt{(1 + a + r)^2 - 4ar}}{1 + a + r + \sqrt{(1 + a + r)^2 - 4ar}} = \frac{1 + a + r - \sqrt{(1 + a + r)^2 - 4ar}}{2\sqrt{(1 + a + r)^2 - 4ar}}$$

Time to peak contrast

$$t_{peak} = \frac{\rho_1 c_1}{h} \frac{t_o}{\sqrt{(1+a+r)^2 - 4ar}} \ln \left(\frac{1+a+r+\sqrt{(1+a+r)^2 - 4ar}}{1+a+r-\sqrt{(1+a+r)^2 - 4ar}} \right)$$





Fiber Sensors



Fiber Sensors are Enabling





- Smart skins
- Smart patches
- Smart Materials
- Functional Materials (ex. Conformal antennas)
- · Chemical and Biological detection in paints
- Designs for Inspection and LO materials: New and advanced structures and materials make NDI inspections very difficult
- Flight change due to combat or system damage
- Testing and Validation of structures and components
- Real-time in-flight testing and validation
- Waste Monitoring



Present System Limitations F-18 E/F Full Scale Fatigue Test








requires a calibration file. Special care has to be taken to requires a minimum of two electrical leads. Each sensor Wiring for strain sensor instrumentation during a full scale fatigue test of F-18 aircraft. Every sensor avoid EMI



Opera Tipor Door



POLYIMEDE BUFFER COATING




BRAGG GRATING



Health Monitoring System




Health Monitoring System




Strain/Temperature Monitoring System




Bondline Monitoring System



AE Monitoring System



Corrosion Monitoring System







VIVITION IN



- Determine Acoustic Emission sensitivity of Bragg Gratings
- Determine methods to enhance AE sensitivity of the sensors
- Study and optimize different demodulation schemes
- Evaluate different data acquisition, analysis and storage
- Simultaneously monitor strains, temperature, AE






Wavelength


$$\Delta I = 2n_p \cdot I \cdot J_1(\lambda \cdot \frac{A}{\Lambda_{oB}^2}) \cdot \sin(k \cdot \frac{L}{2}) \cdot \sin(\omega \cdot t)$$




AE Sensitivity










• Acoustic Emission event detected with a single fiber-optic Bragg grating



NAVAL AIR WARFARE CENTER, AIRCRAFT DIVISION, PAUXENT RIVER, MD





SERDP



SERDP Program



Innovative Nondestructive Evaluation (NDE) Cracking & Corrosion Under Coatings Technologies for the Inspection of **PP-1134**


Dr. Ignacio Perez
Naval Air Warfare Center
Aircraft Division
Materials Division
PerezIM@navair.navy.mil

Ms. Michele Novack
Naval Surface Warfare Center
Carderock Division
Metals Department
NovackMR@nswccd.navy.mil



Typical Aircraft Corrosion & Crack Scenarios









Microwave Technology



- Measure material dielectric properties
- Modify the current CSU microwave NDE model to include the effects of a coating and capability to identify corrosion sites and cracks within one instrument
- Design and prototype handheld instruments
- Conduct lab & field trial evaluations
- Refine design



Pre-prototype 10 GHz Shipboard CUP Detection System



Incident Angle Tuning for Crack Defect Detection



Ultrasound Imaging




Study/model interaction between ultrasonic field and corrosion sites and cracks

- ThroughTransmission
- Shear Wave
- Scattering vs angle
- Guided mode scattering
- Evaluate utility of Lamb and Rayleigh waves
- Optimize hardware

WAVES

Conduct lab & field trial evaluations







UT Imaging Concept



Liquid Filled Sound Wave Imaging Probe:








Exfoliation corrosion around rivets inspected real time using Ultrasound.








Inspection of a composite panel with built in imperfections using Ultrasound Imaging




PEG Data





A Normal quarter in the water tank shows that the Sound Imager can detect changes in surface contour.

Inspection of damaged composite panel





NAVAL AIR WARFARE CENTER, AIRCRAFT DIVISION, PAUXENT RIVER, MD



Novel Illtrasound Imaging Technique








- Uses 128 x 128 sensor array of PVDF ultrasound sensitive elements
- PVDF responds to ultrasound over broad range of frequencies
- Readout method is microelectronic CCD multiplexer




Immersion System






Camera Enclosure





Medical





http://www.imperiuminc.com/

NAVAL AIR WARFARE CENTER, AIRCRAFT DIVISION, PAUXENT RIVER, MD



Heat Damage of Composites



Problem

composite materials can loose up to 70% of their interlaminar damage because they are meant to find mechanical damage exposure. Conventional NDE methods cannot detect this shear strength do to chemical changes resulting from heat Mechanical test data shows that many organic matrix such as cracks and material loss

Solution


Experiments have shown that the fluorescent spectrum of the place in the materials when exposed to heat. This change in the fluorescence spectrum can be used as a measurement of material changes as a result of chemical changes that take the level of heat damage in the material



LIF Concept



- The composite is illuminated using a laser
- The laser light excites electrons to higher energy states
- When the electrons return to their natural state, light is emitted at a longer wavelength (fluorescence)
- The spectrum of the fluoresced light is extremely sensitive to variations in material properties
- Previous work has demonstrated that the fluorescent spectrum changes as organic matrix composite materials are subjected to heat






Portable LIF Measurement Concept



- The portable LIF measurement concept is identical to that of the imaging system except the measurements are made at a single point
- A email lacor is used in conjunction with a fiber optic emitting and receiving probe to illuminate the surface and gather the fluoresced light
- An optical spectrum analyzer is used to determine the wavelength at which the peak fluorescence







Portable LIF System Future Work



Work planned during the remainder of 1999

- Optimize photon collection efficiency
- Collect data on a variety of samples
- Compare portable spectrum data with that from the imaging system

Work planned in 2000


- Develop software algorithms filter data and identify peak location
- Convert system to a laptop-based configuration
- Correlate structural test data and spectrometer data
- Develop software algorithms to present data in a user friendly format




LIF Imaging Concept



- Using filters and a digital camera the fluorescent light can be captured and false colored images can be created
- Previous work demonstrated the feasibility of creating intensity-based images within a narrow (30nm) spectrum
- Current work involves analyzing the entire fluorescent spectrum and creating images based on the wavelength at which peak fluorescence occurs
- Spectrum analysis is accomplished using an acousto-optical tunable filter









LIF Imaging System Configuration







Filter Wheel



LIF Imaging System Status



- AOTF functional and operation successfully demonstrated
- Laser illumination successfully demonstrated
- Computer control software module developed for the AOTF
- System fully integrated and demonstration of imaging at different wavelengths completed



LIF Imaging System Future Work



Work planned during the remainder of 1999

- Incorporate high pass filter to eliminate reflected laser light
- Optimize camera and tunable filter settings
- Collect images from a variety of heat damaged samples
- Compare results with those from the portable system

Work planned for 2000

- Optimize system configuration for portability and data collection speed and ease
- Correlate structural test data and spectrometer data
- Incorporate structurally significant damage thresholds into image
- Develop software algorithms to facilitate easy data acquisition and present it in a user friendly format